



| LE ARMATURE DELLA TRAVE | 28-10 | E | 1-13 | VEDI TRAVE | 1-4 | DEL DIS. 9A |
|-------------------------|-------|---|-------|------------|-------|-------------|
| " | 27-18 | " | 10-2 | " | 47-40 | " |
| " | 26-17 | " | 12-3 | " | 48-50 | " |
| " | 17-17 | " | 12-9 | " | 41-50 | " |
| " | 16-15 | " | 13-14 | " | 51-38 | " |
| " | 19-15 | " | 9-14 | " | 38-27 | " |

L'IMPRESA

22

VISTO: si appro
 L'INGEGNERE CAPO
 DIRETTORE DEI LAVORI
 (Dr. Ing. Mario Parisi)



140
 15
 12
 27
 11.φ6/20