

ACCIAIO Aq. 60÷70
AD ADERENZA MIGLIORATA


GESTIONE CASE LAVORATORI		Intervento N° 1312		stazione appaltante I A C P	
(regge 14-2-1963)					
QUARTIERE SELIA BRINDISI				data 2-11-77 pag. 492 3 _B	
"GRUPPO" di "PARRICIDIO" di "RESISTIVO BARRING"				archivio	
				note	
EDILIZIA	ing. Gaudenzi	STRUTTURE	ing. F. Pire		
EDILIZIA	ing. Padiglione	impianti	ing. P. Pirelli		
EDILIZIA	ing. Gaudenzi	PROGRAMMAZ.	ing. A. Madani		
EDILIZIA	ing. I. Perrelli	PROGRAMMAZ.	ing. L. Patti		
EDILIZIA	ing. L. Patti	PROGRAMMAZ.	ing. E. Romanini		
EDILIZIA	ing. P. Padiglione	COORDINATORE	ing. A. Madani		
EDILIZIA	ing. P. Padiglione	DIREZIONE	I A C P		
STRUTTURE	ing. A. Madani	controllo			

Fig. 10

Fig. 11

QUOTA D'IMPOSTA

0.5

PAVIMENTO

MASSETO

VESPAIO

+0.15

-0

magrione

Technical drawing of a wall section. The wall is labeled "MURAZIONE" at the bottom. The top surface is labeled "PAVIMENTO" and "10/10". The height of the wall is indicated as "650". The drawing is labeled "QUOTA D'INPOSTA" on the left and "D" on the right.

**N.B. IN TUTTE LE FONDAZIONI
PREVEDERE MAGRONE $H=10$ cm.**

